

C.S.

PWD
Miscellaneous
No. 31930

1930

Col Eng

SUBJECT.

1930

PWD

10th July

Previous Paper.

Notice to men regarding the danger of wearing loose clothing when in close proximity to machinery in motion

MINUTES.

① Minute from Col Eng. 10/7/30

y. z. Schmitt to approve

Hon C.S

Please. Charge P. W. D.

AH.

10/30
7

10.7.30

"Penguin" H.T.
12.7.30.

Passed to Printer 14/7/30
W.D.A.S.

Hon Col. Engineer

To note.
W.D.A.S.
14/7/30

Subsequent Paper.

Hon Col. Sec.

Noted

W. Roberts

14-7-30.

Hon Col. Eng.

Fifteen notices. Herewith for
withdrawal, please.

~~W.R.~~ for CS. 22/7/30

Hon. Colonial Secretary.

withdrawn

15 IP copies of notices

W.R. for CS.
22/7/30.

PA. 23/11/30

①
PUBLIC WORKS DEPARTMENT.

W A R N I N G .

**Please keep clear of belting.
Men are warned not to wear loose clothing when working near or on machinery in motion.**