AGR/QUA/1#1

LIVE STOCK

(Quarantine Station)

884/23 No.

1923

H. E. The Acting Governor

C.S.

SUBJECT.

 $192 \ 3$

Work required to be done at Quarantine Station.

15th November

Previous Paper.

MINUTES.

Minute from A.E. the acting governor of 19th abovember 1928 - Enel 1

Colonal Engineer, Referred

The Hon. Col. Secy.,

Noted .

- 2. Iron guttering is not at present in stock. The existing wooden guttering has been examined and it is considered that a coating of pitch on the inside of guttering, as suggested by Mr Atkins, would prevent leaking and would well repay its cost.
- The cleaning up of the paddock also of the inside of the shed has been put in hand and arrangements have been made for the manure and firewood to be carted to Government House.
- The broken hay-racks were found to be beyond repair and the work of making new ones was put in hand some days ago: These have been completed and delivered at the Quarantine station. Repairs to troughs, gratings etc. in the shed have also been done. 5. It is hoped/

alu. 11.

Subsequent Paper.

It is hoped to complete all the work required at the Station next week.

W. Noyc

for Colonial Engineer.

23/11/23.

1/6. Submitted GRER 17 Oi Cfsee 24 Nov 1923

Thankyn This is salisfeeling The new Lay racks skould be kept in ide The shed until required and best the back Mere after the animals is quaranting have been freed. The previous packs dehicorched Mungh weather. The words pollering should be could an sufferted presuming that the water will ut be sported for mukey ttttt 26 Nov. 2.3 Colonial Teng news. To whe GRASS Oichsee 26 Work 1923

The Hon. Col. Secy.,

The hay racks have been placed inside the shed and work required has been completed.

> Assasely. Colonial Engineer. 30/11/23.

Setter from ag Stack hishector of 26" March 1924 - Enel Wieker and march ogget To OS place. The work i necessary till 27 had 24 Referred. 17 Biefste 28 March 1924 Colonial Engineer.

The Hon; Col; Sacretary.

No ted.

2. As soon as the weather is favourable the work

will be put in hand. To be charged to P.W.R. FO. Upkeep of Quarantine shed and paddock. ? Bisisarchy. Colonial Engineer.

3/4/24.

J. Submitted 37 april 1921 tittell & april 24 Colonial Engineer

e Hon. Col. Secy.,

Thank you. Work has been completed.

Colonial Engineer.

9/4/24.

163



to The Officer-in-Charge of the Secretariat.

The ag: Chief his feels of stock saw me yesterday about work still required to be done at the Granachine Station: -(1) The Gooden fullering unw the shed leak very badly and very little water reaches the hock. If in Jullering is available it should be fut up and the worke falle removed his alkens ruffert as an alteralise that the way pilet might be pert in the word to prevent leaking (2) Then should be a general clean up of the hanne and all NO hit of word lying about the querantine faddock. The , hould be carted up to Bur! Homes (3) The broken Layrack artists the shed should be taken to the P.W. D. for refair The is ide of the shed west be thoroughly cleaned not I Knick his Basely book a water of the Last three items but withing I as been I see yet ttttt 19 Nov. 20

Stanley 26: 1924. The Honorable he bolonial Sevetary Si.

I have the honor to forward for
the information of H. E. The Governor.

I have inspected the work done at
the quarantine station by the
fusioner, according to my instruction
the hay tacks have had a costs
of paid outside, and I cost There now remains at the station I gratings scraper, i miser, I fond from I sq. fared Short, I cutch I would suggest that all he woodwar tound the Station especially doors be banked to Station a locks viled before the lumiter selection of the telephone instrument by the tolephone instrument blocks to the banked before the boundable Booley. I am. Your bedient Servant acting Chief Insp. of Stock